

Michael O. Leavitt Governor Ted Stewart Executive Director James W. Carter Division Director 1594 West North Temple, Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

September 26, 1997

TO:

Minerals File

FROM:

Tony Gallegos, Reclamation Engineer

RE:

Site Inspection, Co-Op Mining Company, Co-op Placer Mine, S/015/052, Emery County,

Utah

Date of Inspection:

July 29, 1997

Time of Inspection:

1230 - 1255

Conditions:

Partly cloudy, mild

Participants:

Tony Gallegos, DOGM

Purpose of Inspection:

To examine the mine site while in the area

At the time of this inspection, there were no signs of recent mining activity at the three pad areas located along the access road. Photographs were taken of these pad areas from the opposite side of the canyon. The largest pad area was visited and examined more closely. Several photographs were taken of this pad area.

At this time there are no concerns with the amount of surface disturbance at the site. It is still less than five acres. The access road going beyond the work pads, along the cliff face is still blocked by a rock fall.

jb

cc:

Carl Kingston, Co-Op Mining Co. Dean Nyffeler, BLM, Price Field Office

S015052.ins